









ASSEMBLY INSTRUCTIONS /MONTAGEANLEITUNGEN

*Parental supervision required/
elterliche Aufsicht erforderlich*


Gacek S.C PIKLER SKŁADANY SZKRAB




5 904473 535777 >



1




2




x1 20 mm

x 1 SZT 70 MM




x 2 SZT 55 MM



x1 20 mm

1


2



1x 370 mm




x2




x1 35 mm

x1 20 mm




x 2 SZT 55 MM



1x 370 mm




x2



1x 400 mm



x2





x1 20 mm




x 1 SZT 70 MM

x1 35 mm





x 2 SZT M6 X 70




x 2




x 2 SZT M6 X 50



x 2 SZT M6 X 50



x 2



x 2

548 mm x 2

600 mm



X6

